National Transportation Safety Board FACTUAL REPERT AVIATION

NTSB ID: DCA03MA008 Aircraft Registration Number: N41BE

Occurrence Date: 10/25/2002 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Eveleth	MN		0000	CST	
Airport Proximity: Off Airport/Airstrip	Distance Fror	n Landing Facility:	2	Direction Fro	m Airport:

Aircraft Information Summary

7 thorate information Cariffiary		
Aircraft Manufacturer	Model/Series	Type of Aircraft
Beech	King Air 100	Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

The Board's full report is available at http://www.ntsb.gov/publictn/2003/AAR0303.pdf

On October 25, 2002, about 1022 central daylight time, a Raytheon (Beechcraft) King Air A100, N41BE, operated by Aviation Charter, Inc., crashed while the flight crew was attempting to execute the VOR approach to runway 27 at Eveleth-Virginia Municipal Airport, Eveleth, Minnesota. The crash site was located about 1.8 nautical miles southeast of the approach end of runway 27. The two pilots and six passengers were killed, and the airplane was destroyed by impact forces and a postcrash fire. The airplane was being operated under the provisions of 14 Code of Federal Regulations Part 135 as an on-demand passenger charter flight. Instrument meteorological conditions prevailed for the flight, which operated on an instrument flight rules flight plan.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DCA03MA008

Occurrence Date: 10/25/2002

AVIATION	AVIATION Occurrence Type: Accident												
Landing Facility/Approach In	formation												
Airport Name			Airport ID:	А	irport Elevat	ion	Run	way Used	Runwa	Runway Length		Runv	vay Width
EVELETH-VIRGINIA MUNI	EVM		1369 Ft.	MSL	. 27								
Runway Surface Type:													
Runway Surface Condition:													
Type Instrument Approach: VOR/	DME												
VFR Approach/Landing:													
Aircraft Information													
Aircraft Manufacturer			Mode								Numbe	er	
Beech			King	g Air	100					B-24	5		
Airworthiness Certificate(s): Norm	Airworthiness Certificate(s): Normal												
Landing Gear Type: Retractable	- Tricycle												
Homebuilt Aircraft? No	uilt Aircraft? No Number of Seats: Certified Max Gross Wt. LBS Num						Numbe	Number of Engines		: 2			
* ''				Engine Manufacturer: Model/Series: PT6A-28								d Power: HP	
- Aircraft Inspection Information													
Type of Last Inspection Dat			Date of La	Date of Last Inspection Time Since			nce Last Inspection Hours			Airframe Total Time Hours			
Emergency Leaster Transmitter /	TIT) Information												
- Emergency Locator Transmitter (<u> </u>	od2 No				EI 7	r Aidad i	n Locating A	ooidont C	Sito 2 Nic	<u> </u>		
	ELT Installed? Yes ELT Operated? No ELT Aided in Locating Accident Site? No												
·	Owner/Operator Information Registered Aircraft Owner Street Address												
Registered Aircraft Owner													
				City State							Zip Code		
Operator of Aircraft	Street Address												
Operator of Aircraft				9960 Flying Cloud Dr. City							Stat	ie	Zip Code
/ Wallott Offactor Inc.					Eden Prairie MN 55347						-		
Operator Does Business As: Operator Designator Code:													
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s)	: On-demand Air T	Гахі											
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Unde	Regulation Flight Conducted Under: Part 135: Air Taxi & Commuter												
Type of Flight Operation Conducted	d: Non-scheduled	; Dome	stic; Pass	seng	er Only								
	Ţ	FACTI	IAI RED	ORT	- AVIATI	ON							Page 2
			LILL IXLL		77 1 177 11	014							5

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DCA03MA008

Occurrence Date: 10/25/2002

AVIATION Occurrence Type: Accident														
First Pilot	Information			•					'					
Name						City					Sta	ate	Date of Birth	Age
On File	On File											On File	55	
Sex: M Seat Occupied: Left Principal Profession: Certificate Number:											-			
Certificate(s): Airline Transport														
Airplane Rating(s): Multi-engine Land; Single-engine Land; Single-engine Sea														
Rotorcraft/0	Glider/LTA: None	e												
Instrument	Rating(s): Airpl	ane												
Instructor R	Rating(s): None	е												
Type Rating	g/Endorsement fo	or Accident/In	ncident Aircra	ft? No			T	Current E	Biennia	al Flight F	Revie	w? 10/2	.002	
Medical Ce	rt.:	Medica	al Cert. Statu	S:					I	Date of La	ast M	edical E	xam:	
		'												
- Flight Tim	e Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Actual	Instrume	ment Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time		5116	200											
Pilot In Con	nmand(PIC)	4602	200								\perp			
Instructor									_		_			
Last 90 Day	/S	101									_			
Last 30 Day		36						1			\dashv			
Last 24 Hou		1										Π,		
Seatbelt Us	sed?	Shou	ılder Harness	Used?			OXIC	cology Pe	erform	ed?		Se	econd Pilot?	
Flight Pla	n/Itinerary													
	ht Plan Filed: IF	 R												
Departure F						T	State	e T	Airport Identifier			Departure Time		Time Zone
ST PAUL	<u> </u>						MN		STP					
Destination							State	e	Airpo	rt Identifie	er			
EVELETH							MN EVM							
Type of Cle	earance:													
Type of Air	space:													
Weather	Information													
Source of I		Service Sta	tion											
Method of	Briefing:													
				FACTUAL	L REPORT	- AVIA	TIO	N						Page 3

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DCA03MA008

Occurrence Date: 10/25/2002

	ETYBOR		Oc	Occurrence Type: Accident									
Weather Information													
WOF ID	Observation Time	Time Zone	WOF	Elevation	on	WOF D	istance Fr	om Acci	dent Site Direction From Acciden			Accident Si	te
EVM	1014	CDT	1	380 Ft.	MSL				2 NM	315 Deg.			. Mag.
Sky/Lowes	st Cloud Condition: Scat	tered					400 Ft. A	AGL	Condition of Light: Day				
Lowest Ce	illing: Overcast		-	700 Ft.	AGL	Visib	oility:	3	SM	Altimeter: 30.06			"Hg
Temperatu	ure: 1 °C	Dew Point:		0 °C	Wind	Direction	:			Der	nsity Altitude:		Ft.
Wind Spee	ed: Calm	Gusts:			Weath	ner Cond	tions at Ac	cident S	ite: Instrume	ent C	Conditions		
Visibility (F	RVR): Ft.	Visibilit	y (RVV)	•	SM	Intensit	ty of Precip	oitation:	Light				
Restriction	s to Visibility:												
Type of Pro	Type of Precipitation: Snow												
Accident	Accident Information												
Aircraft Da	mage: Destroyed		Airo	craft Fire	: Grou	nd			Aircraft Exp	losio	n		
Classificati	ion: U.S. Registered/L	J.S. Soil											
- Injury Su	mmary Matrix	Fatal	Serious	Mino	-	None	TOTAL						
First Pi	ilot	1						1					
Second	d Pilot	1						1					
Studen	nt Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin /	Attendants							7					
Other (Crew							7					
Passer	ngers	6						6					
- TOTAL A	ABOARD -	8			\top			8					
Other (Ground	0	0		0			0					
- GRANI	O TOTAL -	8	0	 	0			8					

National Transportation Safety Board
National Transportation Safety Board
FACTUAL REPORT

NTSB ID: DCA03MA008

FACTUAL REPORT	Occurrence Date: 10/25/2002	
AVIATION	Occurrence Type: Accident	
Administrative Information		
Investigator-In-Charge (IIC)		
Frank Hilldrup		
Additional Persons Participating in This Accident/Incide	ent Investigation:	